


Elcometer 102 Needle Pressure Gauge

The Elcometer 102 Needle Pressure Gauge is designed to measure air pressure in blast and air hoses.

Pressure drop is responsible for decreased production rates, increased abrasive consumption and reduced anchor profile in abrasive blasting systems.



How to use a Needle Pressure Gauge



Technical Specification

Part Number	Description
E102-A	Elcometer 102 Needle Pressure Gauge
Measuring Range	0 - 300psi (0 - 20bar)
Pressure Limitations	Steady: 3/4 x full scale value Fluctuating: 2/3 x full scale value Short Time: Full scale value
Operating Temperature	-20°C to 60°C (-4°F to 140°F)
Dimensions	133 x 58 x 28.5mm (5.24 x 2.28 x 1.12") Weight 110g (3.88oz)
Packing List	Elcometer 102 Needle Pressure Gauge, needle (x2), needle protector, protective pouch and operating instructions