


## Elcometer 102 Needle Pressure Gauge

The Elcometer 102 Needle Pressure Gauge is designed to measure air pressure in blast and air hoses.

Pressure drop is responsible for decreased production rates, increased abrasive consumption and reduced anchor profile in abrasive blasting systems.



### How to use a Needle Pressure Gauge



### Technical Specification

Part Number	Description
<b>E102-A</b>	Elcometer 102 Needle Pressure Gauge
<b>T10229425</b>	Replacement Needle (Pack of 2)
Measuring Range	0 - 300psi (0 - 20bar)
Pressure Limitations	Steady: 3/4 x full scale value Fluctuating: 2/3 x full scale value Short Time: Full scale value
Operating Temperature	-20°C to 60°C (-4°F to 140°F)
Dimensions	133 x 58 x 28.5mm (5.24 x 2.28 x 1.12")
Weight	110g (3.88oz)
Packing List	Elcometer 102 Needle Pressure Gauge, pressure gauge guard, spare hypodermic needle, protective pouch and operating instructions